

Firmware Release Note



Model: CLX-8640, 8650 Series

Date: 5-Oct-2016

Version	Category	Change Description
V6.E6.03.EC1512.02 (5-Oct-2016)	Fix Defect	Enhance toner yield and accuracy.(Especially for the low coverage and low job duty printing pattern)
V6.E6.03.EC1512.01 (18-Feb-2016)	Fix Defect	Open SSL issue for supporting Daimler's IPV6 tests
		Polaris Color) CLX-9201, Printing message in Job status
		Crash observed when User does two Searchable PDF job. And cancel first Searchable PDFjob [Security][PolarisC] Security Update - NSRI Security Recommendations (1/15)
V6.E6.03.EC1512.00 (17-Jan-2016)	Fix Defect	Daimler reported some issues found during IPV6 tests
V5.E6.03 (15-Jan-2016)	Fix Defect	Scan to Email fails in specific environmnet.
		When a user scans to email (scan to me) using the prepopulated data on the device it scans OK to Intermittently, "server connection failure" shows during LDAP Authentication.
		Scan to Server Email notification was sent even when the option was disabled from SWS.
V5.D6.15 (15-Dec-2015)	Fix Defect	SNTP/DST - Timezone issue for Chile, Ukraine and USA Eastern Time
		Machine reboot continuously with 1 hour period, after DST(Daylight Saving Time) clock shift
V6.D6.08 (2-Apr-2015)	Fix Defect	<ol style="list-style-type: none"> 1. Improve Toner Gauge Accuracy <ul style="list-style-type: none"> - Toner is empty when gauge is over 40%. - Toner gauge decreases slower than actual toner usage. - Change gauge algorithm from using dot to using Slit. 2. Pressure Roller pollution prevention through the fusibility improvement (modify fuser CTS table) <ul style="list-style-type: none"> - Change the pattern of "Fuser Cleaning Mode". 3. Improve Band error at back side that is frequently occured in case of high tempature.
V6.D6.06 (12-Jan-2015)	Fix Defect	1. After HDD changing, some count of Usage Report is incorrect.
	Fix Defect	11. IP address was not renewed with DHCP server if device is creating Hibernation Image.
	Fix Defect	21. Dotted lines in a table are disappeared in color mode printing with Excel office 2011 and Mac OS
	Add Func.	31. Disable Fax receive forward in SWS fax settings menu when solution applications is installed.
	Change Spec.	1. Support BCPS applications on XOA-Web version
V6.C6.41 (5-Jan-2015)	Fix Defect	1. Improvement - Supplement copy image cutoff in case of copying
		1. Band image happen when Gray pattern is printed.
V6.C6.40 (20-Nov-2014)	Fix Defect	1. Reset sometimes after memory clear & sort power on.
		2. Reduce the noisy on Platen Motor.
		3. Powersave timeout & option does not be applied
V6.C6.34 (18-Sep-2014)	Add Func.	1. HID Global R54270001-Con model supported.
	Change Spec	1. Support Israel Hebrew Dos Printing in Polaris.
	Fix Defect	1. Other user name is displayed on LUI even another user's card is used for authentication.
V6.C6.24 (28-Jan-2014)	Add Func.	1. Add to support WLAN and BCPS solution.
	Delete Func.	1. Delete Fuser product date (by Manufacturing]
	Change Spec	1. [LMS] New SLM specification should be support.
	Fix Defect	1. macro parser misoperation(ellipsis) and text positioning error. 2. Oracle printing issue

※ Note

- Please do not turn off the printer and your computer until firmware update finishes.
 - If you are using USB connection, disconnect all other USB printers from the PC.
 - The firmware update you are about to install has been tested for compatibility with Samsung toner cartridge products ONLY.
- Installing The upgrade may cause a non-Samsung toner cartridge to malfunction.
- Do not run your printer during the firmware update.(Do not have any print job)