



Firmware NEXUS_01_16_00.8 is available

For HP Latex 3x0 Printer Series

October 2019

HP Latex 3X0 Printer Series' (310/330/360/370) latest firmware version is now available to download and install. This firmware includes significant new features and fixes.

HP strongly recommends upgrading to the latest firmware for all units as it includes significant improvements.

Related links:
www.hp.com/go/latex/

Printers related to this article
[HP Latex 3x0 Printer Series](#)

Important notes

- Please note that the printer will automatically reboot 2 times until the firmware upgrade process is completed successfully.
- DO NOT use this firmware for new printer installations with SNs below MY5324902N and firmware version below FW 04_10.3, in this case contact your HP representative.

Where to find firmware NEXUS_01_16_00.8

Web

<http://www8.hp.com/us/en/drivers.html>

Find your product -> Select your OS -> Download the *.fmw file -> Install it via USB or EWS.






Online

Printer -> Check Updates -> Check Now.



Summary of changes

Here are the improvements achieved with the firmware version NEXUS_01_16_00.8:

-  1. Compatibility with the Configuration Center application
-  2. Fix for Take-up Reel button grayed out in the Front Panel menu after FW upgrade.
-  3. Support to Energy Star 3.0 requirements
-  4. Minor internal changes to improve the printer's functionality
-  5. Possibility to downgrade to previous version

Compatibility with the Configuration Centre application


Changes

Possibility to set up the printer and manage the substrates configuration using the Configuration Centre.

Details

For more information about the NEW Configuration Center application, please see:

- How to Use the HP Configuration Center:
<https://youtu.be/AWTe1ue6uYs>
- How to Deploy and Back Up a Substrate Configuration with HP Configuration Center:
<https://youtu.be/wao1HWDCj9k>
- More materials about PrintOS on LKC:
<https://hplatexknowledgecenter.com/blog/categories/software-solutions>






Fix for the Take-up Reel button grayed out in the Front Panel menu after Firmware upgrade

Changes

This firmware permanently solves the issue with the Take-up Reel button on the Front Panel becoming inaccessible.

Details

There was a known issue which mainly appeared after upgrading the firmware to the previous version (NEXUS_03_14_00.8). The Take-up Reel button on the Front Panel became grayed out, inaccessible.



Support to Energy Star 3.0 requirements

Changes

With this firmware upgrade the printers are fully Energy Star 3.0 compliant.

Details

The maximum time to sleep can be now set is 1 hour.



Minor internal changes to improve the printer's functionality

Possibility to downgrade to previous version

Changes

Downgrading to previous version is possible.

