



# Firmware Release Note

|                            |                          |
|----------------------------|--------------------------|
| <b>Model: K2200 Series</b> | <b>Date: 29-Jun-2016</b> |
|----------------------------|--------------------------|

| Version                             | Category   | Change Description  |
|-------------------------------------|--|---|
| <b>V3.00.01.35</b><br>(29-Jun-2016) | Fix Defect   | 1. Fix toner yield issue. (Even though much toner remains in toner cartridge, the machine shows "Prepare new toner" message.) |
| <b>V3.00.01.32</b><br>(30-Sep-2015) | Add Func.  | 1. Adjust background is added to copy default menu.   |
| <b>V3.00.01.31</b><br>(15-Jul-2015) | Fix Defect   | 1. Reduce the unwanted waste toner and change the toner supply time&amount correlation.                                       |
| <b>V3.00.01.29</b><br>(2-Feb-2015)  | Fix Defect   | 1. Improve the additional Fuser Offset when it is being down to the lower temperature.  |
| <b>V3.00.01.27</b><br>(19-Dec-2014) | Fix Defect   | 1. Improvement of Fuser Offset.   |
| <b>V3.00.01.26</b><br>(19-Sep-2014) | Fix Defect   | 1. USB printer class is not present at device manager after PC wake up from sleep mode.                                       |
|                                     |  | 2. Print does not work when PJI DOCNAME has spaces around 50th byte.  |
|                                     |  | 3. When 2-1 Copy, the copied papers are out of sequence.  |
|                                     |  | 4. BB Item Delete & Add Recovery Problem  |
|                                     |  | 5. Book copy become fail with A5 paper  |
|                                     |  | 6. Machine reboots while performing scan to pc  |
|                                     |  | 7. Imaging Unit install date does not displayed   |
|                                     |  | 8. Lite SM pop up is not seen in IPV6 Environment   |
|                                     | Add Func.  | 1. Countermeasure against refilled toner cartridge (II)   |
|                                     |  | 2. Not to add more than 10 users for network scanning.  |
| Change Spec.                        | 1. Firmware version's backup function is changed for B2B version             |   |
|                                     | 2. Change Toner Supply Msg Display & Change default Image Density Level(-5). |   |


※ Note

- Please do not turn off the printer and your computer until firmware update finishes.
  - If you are using USB connection, disconnect all other USB printers from the PC.
  - The firmware update you are about to install has been tested for compatibility with Samsung toner cartridge products ONLY.
- Installing The upgrade may cause a non-Samsung toner cartridge to malfunction.
- Do not run your printer during the firmware update.(Do not have any print job)

## How to update the firmware

### If the machine is connected to the PC via USB cable


- 1) Make sure that the machine is connected to the PC with a USB cable.
- 2) Drag the firmware file(\*.hd) and Drop down it on usblast2.exe.  
And then firmware update will be started automatically.




- 3) If completed, the firmware update will be rebooted automatically.

### If the machine is connected to the network

- 1) Open Internet Explorer.  
Enter the machine IP address(http://xxx.xxx.xxx.xxx) of your printer.



- 2) Click 'Login' on the upper right of the SyncThru Web Service.  
And log-in as an administrator.  
(Default ID : admin PW: sec00000)  
※ We recommend you to change the default password for security reasons.
- 3) 'Maintenance'→'Upgrade Wizard' → 'Browse'  
And, Select the firmware file and click 'Next'



- 4) Please follow the instruction on the screen.
- 5) If completed, the firmware update will be rebooted automatically.