

Firmware Release Note

Model : SL-M2021W/XIL, M2021W/XIP	Date :	September 28, 2018
--	---------------	---------------------------

Version	Category	Change Description
V3.07.01.05 (14-Nov, 2014)	Fix Defect	[Google Cloud Print] Fix to the latent issue and enhancement to UI. Google Cloud Print is not perfectly control the "chunked" data. Compatibility of OTG cable. Can not print when PJI DOCNAME has spaces around 50th byte.
V3.07.01.07 (16-Jan, 2015)	Add Func.	Google Cloud Print 2.0 feature
	Fix Defect	Paper jam error doesn't be cleared by pressing the Print Screen button
V3.07.01.10 (5-Feb, 2016)	Fix Defect	Improved the Step Motor compatibility
V3.07.01.11 (5-Feb, 2016)	Add Func.	Apply to Samsung Cloud Print
	Fix Defect	Fix IP changing problem in DHCP mode
V3.07.01.13 (13-May, 2016)	Fix Defect	Enhance JAM problem
V3.07.01.23 (28-Sep, 2018)	Fix Defect	Fix the print quality issues(background, dim and dirty printing)

※ Note

- Please do not turn off the printer and your computer until firmware update finishes.
- If you are using USB connection, disconnect all other USB printers from the PC.
- The firmware update you are about to install has been tested for compatibility with Samsung toner cartridge products ONLY.


Installing The upgrade may cause a non-Samsung toner cartridge to malfunction.

- Do not run your printer during the firmware update.(Do not have any print job)

How to update the firmware using a USB cable.

1. Make sure that the machine is connected to the PC with a USB cable.
2. Drag the firmware file(*.hd) and Drop down it on usblist2.exe.

And then, firmware update will be started automatically.



3. The firmware update will start.

Once the firmware update is complete, the machine will be rebooted automatically.